

2. Work to figured dimensions only. Do not scale drawing.

6. Sizes of proprietary items shall be checked with manufacturer.

5. Proprietary items shall be fixed in strict accordance with manufacturers instructions.

7. The contractor shall be responsible for the coordination of structure, finishes and services. M:\Project Section - Current\6284 Kinsale Road\CAD\Planning\Planning 1\(5\) LRI

The contractor is responsible for checking all levels and dimensions on site and shall refer all discrepancies to the Architect
Where appropriate, for details of r.c. structure, or mechanical and electrical details, see Engineers drawings